

Release Note for VigorSwitch P2100

Firmware Version:	2.9.9
Loader Version:	3.5.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	VigorSwitch P2100

New Features

- None.

Improvement

- Corrected: An issue regarding the maximum number of supported VLANs.
- Corrected: An issue with syslog format preventing VigorACS from collecting logs correctly.
- Corrected: An issue that writing an empty port description profile in Central Management would not clear the existing settings on the switch.

Known Issue

- Users could not downgrade the firmware below 2.8.x, if the loader version is 3.5.2.

Note

- STP (Spanning Tree Protocol) is enabled by default starting from firmware version 2.9.8, which may result in a slightly longer link-up time for ports.