

Release Note for Vigor2760 Series (Delight)

Firmware Version:	3.8.9.6
Release Type:	Normal
Applied Models:	Vigor2760, Vigor2760n, Vigor2760Vn

DrayTek launches Vigor2760 series – high speed router, perfectly complied with VDSL2/ADSL2/ADSL2+ environment including Vigor2760, Vigor2760n and Vigor2760Vn for speed-wanted customers. For more details of the product information, please visit our website on <http://www.draytek.com>.

New Features

- None.

Improvement

- Improved: Improve Web GUI Security (CVE-2022-32548).
- Improved: Improve the OpenSSL security (CVE-2022-0778).

File and Modem Code

- Vigor2760_v3.8.9.6 (Standard) Provides Annex A modem code 548006_544401, 560816_552011, and Annex B modem code 548006_544512, 551716_553312.
- Vigor2760_v3.8.9.6_VECTOR1 Provides Annex A modem code 567517_562301, 566f07_562701, and Annex B modem code 565607_567002, 565606_567002.
- Vigor2760_v3.8.9.6_VECTOR2 Provides Annex A modem code 574307_571801, 573807_571701, and Annex B modem code 573307_571c02, 565607_567002.
- Vigor2760_v3.8.9.6_VECTOR3 Provides Annex A modem code 576d17_572801, 574307_571801, and Annex B modem code 573307_571c02, 565607_567002.
- Vigor2760_v3.8.9.6_VECTOR4 Provides Annex A modem code 579F17_573F01, 573807_571701, and Annex B modem code 573307_571c02, 565607_567002.
- Vigor2760_v3.8.9.6_VECTOR5 Provides Annex A modem code 57c817_575a11, 573807_571701, and Annex B modem code 573307_571c02, 565607_567002.

Note: For DSL models, there will be two folders: STD and VECTOR. The files in VECTOR folder implement a new DSL driver, which supports G.Vectoring on VDSL. If you're using a VDSL line, VECTOR firmware may bring out better performance; however, please consult your ISP to check if G.Vectoring is required. We also provide several versions of Vector firmware to avoid the interoperability issue. You could just try the other one if the one you use cannot synchronize or get the speed that you expected.

Known Issue

- None.